

Corner Applicator Tune Up

Keep your Corner Applicator in top condition. We'll professionally clean the tool then change the pressure plate wiper and the seal at the hinge to ensure leak-free performance. Finally, we'll lubricate all the moving parts and adjust the tool to factory settings. The following parts will be changed as part of this Tune Up:

Quantity	ltem	Description	
For the 8" Corner Applicator			
1	350008	8" Applicator Wiper	
1	502019	Seal	
For the 7" Corner Applicator			
1	500028	7" Applicator Wiper	
1	700029	Rushing Liner	

Price: Plus Shipping	\$55.00
-------------------------	---------

\$97.00 for Residents of AK or HI Including FedEx 2-Day Shipping

Important: The Corner Applicator body must be in good condition or the Tune Up may not restore the tool to perfect working condition. Our Expert Technicians will advise you of any recommended additional repairs when the tool is examined.

© 2019 Axia Acquisition Corporation. All Rights reserved.

Superseded Parts Policy: As part of our continuous product improvement, certain parts are sometimes superseded by an improved or updated part. In these cases, the actual model numbers of the parts we replace may differ from those listed in this literature but we guarantee that all the parts listed for each repair package will be replaced in regards to placement and function within the tool.

Warranty on Repairs: We warranty all repairs will be free from defects in parts and workmanship for a period of 1 year from the date of the repair. This applies only to the specific parts that were replaced as part of the repair.