



## Nail Spotter Tune Up

Keep your Nail Spotters in top condition. This Tune Up includes replacement and calibration of the blade, replacement of the special rivet behind skid to ensure proper functioning of skid on wall and replacement of the friction washers at the handle connection for secure fastening of handle to the tool. After we've changed these parts we'll give the Nail Spotter a professional cleaning, lubricate all the moving parts and adjust the tool to factory settings. The following parts will be changed as part of this Tune Up:

Quantity	Item	Description
<b>For the 2" Nail Spotter</b>		
1	600005F	2" Carbide Blade
1	602029F	Special Rivet
4	609018	Washer
1	609020	Friction Washer

<b>For the 3" Nail Spotter</b>		
1	650005F	3" Carbide Blade
1	602029F	Special Rivet
4	609018	Washer
1	609020	Friction Washer

**Price: \$65.<sup>00</sup>**  
Plus Shipping

\$105.00 for Residents of AK or HI  
Including FedEx 2-Day Shipping

**Important:** The Nail Spotter body must be in good condition or the Tune Up may not restore the tool to perfect working condition. Our Expert Technicians will advise you of any recommended additional repairs when the tool is examined.

**Superseded Parts Policy:** As part of our continuous product improvement, certain parts are sometimes superseded by an improved or updated part. In these cases, the actual model numbers of the parts we replace may differ from those listed in this literature but we guarantee that all the parts listed for each repair package will be replaced in regards to placement and function within the tool.

**Warranty on Repairs:** We warranty all repairs will be free from defects in parts and workmanship for a period of 1 year from the date of the repair. This applies only to the specific parts that were replaced as part of the repair.