



## MudRunner® Tune Up

Keep your MudRunner in top condition by periodically replacing the bushings and gaskets that provide smooth, leak-free performance. After we've changed these parts we'll give the MudRunner a professional cleaning, lubricate all the moving parts and adjust the tool to factory settings. The following parts will be changed as part of this Tune Up:

Quantity	Item	Description
1	140012	Control Slide
2	140013	Control Bushings
2	149021	Round Lip U-Cup
1	149028	Nylon Bushing

**Price: \$75.00**  
Plus Shipping

\$200.00 for Residents of AK or HI  
Including FedEx 2-Day Shipping

**Important:** If your MudRunner has other parts that are damaged or excessively worn, the Tune Up may not restore the tool to perfect working condition. Our Expert Technicians will advise you of any recommended additional repairs when the tool is examined.

**Superseded Parts Policy:** As part of our continuous product improvement, certain parts are sometimes superseded by an improved or updated part. In these cases, the actual model numbers of the parts we replace may differ from those listed in this literature but we guarantee that all the parts listed for each repair package will be replaced in regards to placement and function within the tool.

**Warranty on Repairs:** We warranty all repairs will be free from defects in parts and workmanship for a period of 1 year from the date of the repair. This applies only to the specific parts that were replaced as part of the repair.